





























Prototype Testing	
•HALT - Highly Accele	erated Life Test
•HASS - Highly Accelerated Stress Screening	
- FINOS - Filigrilly Accele	Stated Greek Coroning
XP Power	16
Manufacturing Methods	3
•Suppliers	
•Manual Assemi	ibly Methods
	ettings and parameters
caming of se	O
XP Power	17
	<u></u>
System Reliability	
•More Reliable 0	Components
•Redundancy	

XP Power







