

# Underwriters Laboratories (UL LLC) Safety Certification (Manufacturing Factory) Report



Model: JMR1012S05, JMR1012S12, JMR1012S15,  
JMR1012D05, JMR1012D12, JMR1012D15,  
JMR1024S05, JMR1024S12, JMR1024S15,  
JMR1024D05, JMR1024D12, JMR1024D15,  
JMR1048S05, JMR1048S12, JMR1048S15,  
JMR1048D05, JMR1048D12, JMR1048D15

Manufacturing Facility(ies): Motien Technology Co LTD  
9 Keji 2nd Rd Technology Industrial Park  
Tainan 709031 Taiwan

Applicant: XP Power LLC  
15641 Red Hill Ave, Suite 100  
Tustin, CA 92780 USA  
E321744

Listee: Same as Applicant  
Listee File No.:

Report No.: E321744-D1034-1/A0/C0  
Report (Re)Issue Date: 2023-10-06

Standard(s): AAMI ES60601-1:2005,ES60601-1:2005/AMD1 1:2012 , ES60601-1:2005/AMD2:2021, CAN/CSA-C22.2 No. 60601-1:08, CAN/CSA-C22.2 No. 60601-1:14 (including amendment 1) and Amendment 2:2022 (MOD) to CAN/CSA-C22.2 No. 60601-1:14

Additional Standards: None

Report Types: This report consists of the following report types:  
[ Yes ] US Certification (UL Recognition)  
[ Yes ] CAN Certification (cUL Recognition)

You are receiving this report as a Manufacturing Factory for the above-referenced Applicant.

This report covers the Safety evaluation of the referenced model(s) according to the standard(s) specified above.

This report includes portions of the full Applicant report and is designed to support any Follow-Up inspections at the Manufacture's facility.

Please refer to any Supplements to this document for a detailed manufacturer report, which includes information for the Follow-Up Inspection as specified below:

- **Appendix C:** Follow-Up Service Documentation
- **Appendix A:** Enclosures